


## NAV SD Card Removed Error AND One Solution

There are several Forum Treads defining an error I encountered with NAV stopping to work. An early Thread started in October 2020. I started to post in August 25, 2021 when I encountered the issue.

Basically, you get a message on the right side of the driver's center screen on startup that says SD Card Removed. You have to press to eliminate the message. When you subsequently press NAV on the center screen, it tries to load the NAV SD card but gets so far and stops. This was my message in below pic.



Considering the message, I and a number of others including dealers, first assumed it was the contacts on the NAV SD card so we cleaned them. My contact cleaning looked like it worked. But soon the same message. A dealer even installed a new reader. No help.

I even added a 0.032 plastic shim above the card increasing tension on the reader fingers. At first looked like it worked, then like the cleaning, soon the same issue. It was occurring about 1/3 of the time I started the car!

### GOOD CLUE, ONE SOLUTION TO THE ISSUE:

*Z06DevilCar* had the "NAV SD Car Missing" issue with his 2020 Z51 Coupe and posted in January 2021 on this Thread. He was initially confused thinking it was the PDR SD card (as was I until I say the message on the center screen made it obvious which one it was! It was the SD NAV card located in the consol.)

He googled and found this problem not only occurs on the C8 but also other GM products such as Blazer, Camaro, Equinox, Malibu etc. after 2019 with the new NAV. It's reported as very intermittent. Thinking through the sequence of events he realized that one thing he had done the night before was insert a USB Thumb drive with MP3 music and that music was streaming during the NAV startup which does a significant amount of reading from the NAV SD card.

In fact, my SD Card Error started in August 2021 because my XM radio was running out of its free year and I had installed the thumb drive with ~1000 songs I had in my C7 Z51 and Grand Sport! He concluded the USB and the NAV SD card are on the same data bus and during NAV startup, if you are also streaming USB music, the NAV SD Card Reader loading on the bus caused the SD Card error message.

He removed the USB Thumb drive and failures stopped. He then built 2 USB drives with music. The first drive has songs recorded at a bit rate of 160 kbps and lower, the second has songs all recorded at a bit rate of 320 kbps.

To make this problem occur the music must be streaming from the USB drive to the media app while the NAV is starting up. (*In fact, that is how I have my C8 set, music starts when I start the car.*) He tested the 160 kbps USB drive for 3 weeks without a failure. Then replaced that USB drive with the one recorded and 320 kbps and the failure occurred the second time the car was started the car.

The obvious conclusion was that the NAV SD card and the USB media share the same data bus, and with the higher bit rate music playing while trying the read from the NAV SD card during its initiation creates "interference" on the data bus. The SD Card control software is not able to recover thus the "NAV SD Card Removed" message.

Doing some additional research, he went to a couple of dealers who thought he was nuts or wanted to remove the center console and replace the SD Card reader. He notes the service departments in the Chevy dealers don't acknowledge this problem and want to reseat your SD card and send you on your way. He mentioned that this problem exists on other GM brands with the new NAV. I found a Technical Service Bulletin 19-NA-279 with the Subject - Radio Software Version V807. I looked at the Bulletin and although not for the C8 it states:

"SD Card Error code 0x40000 • SD Card Removed message when card has not been removed • Cause The cause of the condition may be software anomalies."

## Bottom Line: What GM Bulletin States Is No Help!

In fact, my solution followed *Z06DevilCar's* advice. How I achieved the positive result is interesting.

With my Daughter's help, loaded open office software she suggested that allows any song "Bit Rate" to be adjusted. However, the free one she suggested has an interesting feature that caused the solution to happen serendipitously. Not sure why but when I simply copied and pasted my whole Thumb Drive file with ~1000 songs in the "open office program" it automatically lowers the bit rate for songs higher than 160 kbps to that level. It left lower bit rates alone!

Didn't even run the program, which would have taken a lot of time to change some 300 songs to a lower bit rate with each done separately. Just copied and pasted the file as it appeared once it was in the open office program back to a Thumb drive!

The following photos show what was done.

Note: Works 99+% For Me- Occasionally Get The "SD Card Removed" Error.

## **Solution Sequence With Photos**




# Now What Software is Needed to Change Higher Bit Rate Songs to Max 160 kbps?

Daughter is a former IT Manger at her Alma Mater, Scripps College in Claremont CA. Her area was called Academic Computing where she had to introduce the faculty and students to computers! Was not easy as some old time College Board Members (*and large doners*) were upset because typewriters reduced penmanship skills!

She managed computers set-up in the dorms, and over 30 in what were called PC labs. This job started around 1982 when we didn't even have PCs at our work. She employed a number of student computer assistances who were a big help. I recall her issues with viruses, Professors using copyrighted pics and the College getting sued etc.!

She uses mostly free open office software and suggested a very good one, Audacity



Just copied this file and pasted in a Thumb Drive! IT WORKS!

Oldies But Goodies V ...

Oldies But Goodies, V.,

All-Time Greatest Hits

Oldies But Goodies V ...

The Platters Greatest ...

Oldies But Goodies V ...

Rockin' 70's

Some Hearts

160kbps

160kbps

1604bps

160kbps

160kbps

160kbpr

160kbps

128kbps

Copyright by WA Technology, LLC

Raindrops

Surfin' USA

Tequile

Watter

Rainy Night In Georgia

Since I Don't Have You

The Great Pretender

Unchained Melody

Dee Clark

Brook Benton

The Skyliners

The Champs

The Platters

The Beach Boys

The Righteous Bro...

Carrie Underwood

o 01 Raindrops

e 01 Surfin' USA

0 01 Tequila

@ 01 Waited

File name

Files of type

@ 01 Rainy Night In Geor ...

0 01 The Great Pretender

9 01 Unchained Melody

MP3Nex

01 Since | Don't Have Y., 1

Network

Open

Cancel

added)

dropped the ones

that exceeded 160

kbps. Now have a

Thumb Drive with

max 160 kbps!

and

## WA Technology

## "56" C8, 2017 Grand Sport & 2014 Z51 Stingray Mods, Info Available As PDFs:



56 PDFs discuss improvements or info about a C8, 2017 Grand Sport, 2014 Z51 Stingray function and/or esthetics. Some are minor and others, like the installing "Low Dust Brake Pads" on C8 & C7s, have detailed information.

Below are the PDF's available. Click on picture or Blue PDF link or copy and paste the PDF link (Blue type) into your browser. Or email me at <u>GUttrachi@aol.com</u> and state the title desired, shown in Yellow:

C8 Install High Wing How To Remove Rear Bumper- Install Wing http://netwelding.com/C8_High_Wing.pdf	
C8, C7 eLSD vs Positraction eLSD is a Modern Dif; Positraction is from 1960s http://netwelding.com/eLSD _VS_Posi.pdf	-o Whee Bip 30%
C8 FWD Hybrid WFWD Hybrid Provides More Power & MPG http://netwelding.com/C8_FWD_Hybrid.pdf	
C8 Edge Red Engine Cover Engine Cover Matches Valve Covers http://netwelding.com/Engine_Cover.pdf	
C8 Engine Compartment Lights Multicolor Lights Remote operated http://netwelding.com/Engine_Lights.pdf	
C8 Side Skirts & Splitter Install C7 Carbon side skirts & splitter on C8 http://netwelding.com/Side_Skirts.pdf	8
C8 Z51, GS/C7 Z51Ceramic Brake Pads Performance Vettes have dusty brakes. These help! http://netwelding.com/Ceramic_Pads.pdf	
Copyright by WA Technology, LLC	GUttrachi@aol.com

### **C8** Low Restriction Air Intake

Low Restriction Air Filter Why & How To

http://netwelding.com/C8\_Air\_Intake.pdf

C8 & C7 Splitter & C8 Condenser Mesh Mesh Protects AC Condenser & Splitter Install http://netwelding.com/CF\_Splitter.pdf

**C8 NAV SD Card Removed Error** *Error When SD Card and Reader Are Fine* http://netwelding.com/NAV\_SD\_Card.pdf

**C8/GS/C7 Splash Guards** GM splash guards. ACS Best Front Guards for GS. http://netwelding.com/Splash\_Guard.pdf

Jacking a C8/GS/C7 Vette Safely jacking either front only or back & front

http://netwelding.com/Jacking\_A\_C7.pdf

C8 & C7 Plates & Frame; Must Meet South Carolina Law http://netwelding.com/License\_Plate\_Frame.pdf

Change GS/C7 Oil WHY change your own oil and C7 Lifting Methods http://netwelding.com/Changing\_Oil.pdf

C8/GS/C7 Mirror Proximity Alarm Limit switch alarm warns when close to door frame http://netwelding.com/Mirror\_Proximity\_Alarm.pdf

Jacking Pads for C8/GS/C7 Manual says Jacking Pads 2 1/2-inch max OD.. http://netwelding.com/Jacking\_pads.pdf

C8/GS/C7 Radar Power For C7 tapped rear fuse panel. For GS tapped mirror http://netwelding.com/Radar\_Detector\_Power.pdf

**C8 & C7 Wheel Chatter/Hop** Why sharp, low speed turns with cold tires causes the front tires to chatter/hop. http://netwelding.com/Wheel\_Chatter.pdf

C8/GS/C7 Wheel Locks Wheel locks, help protect your expensive wheels. http://netwelding.com/Wheel\_Locks.pdf

Deer Whistle Installed on C8/GS/C7 Do they work? Plus Install Info http://netwelding.com/Deer\_Whistle.pdf C8 & C7 Splitter Protector

Scrape Armor Protection for Splitter http://netwelding.com/Splitter\_Protectors.pdf

Copyright by WA Technology, LLC























#### C8 & C7 Cargo Area Rear cargo area storage device and rear protector http://netwelding.com/Rear\_Cargo\_Area.pdf

C8 Coilover Tower Covers Prevent water from filling Cast aluminum cavities http://netwelding.com/Tower\_Covers.pdf

C8.R Info & GS Rear Diffuser (Fits Any C7) Rear Carbon Flash Composite Diffuser http://netwelding.com/Rear\_Diffuser.pdf

## **GS/C7 Belt Rattle**

Passenger seat belt rattles against the seat back. http://netwelding.com/Eliminate\_Rattle.pdf

Aluminum C7 Chassis and Weld Repair The C7 aluminum chassis. Includes weld repair info. http://netwelding.com/Aluminum\_Chassis.pdf

Manage GS/C7 Spilled Gas & Door Lock Protect when filling gas. Preventing door lock failure. http://netwelding.com/Manage\_Spilled\_Gas.pdf

GS/C7 License Plate & Cargo Lights LED license plate light & cargo area bulbs http://netwelding.com/License\_Plate\_Light.pdf

**GS/C7 Door Panel Protector** Black plastic protector prevents scuffing of door http://netwelding.com/Door\_Panel\_Protector.pdf

GS/C7 Improved Cup Holder A solution to the cup holder spilling http://netwelding.com/Improved\_cup\_Holder.pdf

**C7 Carbon Fiber Grille Bar** Install genuine carbon fiber grille bar overlay http://netwelding.com/CF\_Grille\_Bar.pdf

**Replacing C7 Battery** *Tricks for installing battery!* http://netwelding.com/Battery\_Issues.pdf

GS/C7 Window Valet Lower Windows With FOB Helps Latch Hatch http://netwelding.com/Hatch\_Latch.pdf

## **GS/C7 Blind Spot Mirror**

Smaller rear and side windows cause C7 blind spots. Small "blind spot mirrors" help

http://netwelding.com/Blind\_Spot.pdf

Copyright by WA Technology, LLC























**GS/C7 Skid Pad Protector** *After the air dam, the aluminum "skid pad" hits* http://netwelding.com/Skid\_Pad\_Protector.pdf

GS/C7 OnStar Lights Rear view mirror OnStar LED's, at a quick glance, look like a police car flashing light! This is a fix. http://netwelding.com/OnStar\_Lights.pdf

GS/C7 Skip Shift Eliminator Skip Shift Eliminator install with suggestions on jacking a C7. http://netwelding.com/Skip\_shift\_Eliminator.pdf

**GS/C7 Catch Can & Clean Oil Separator** What is Coking and how to reduce the potential http://netwelding.com/Catch\_Can.pdf

GS MGW Flat Stick Shifter The MGW shifter shortens throw and is more precise http://netwelding.com/MGW\_Shifter.pdf

GS/C7 Round Shift Knob A round shift knob shortens throw on OEM shifter http://netwelding.com/Shift\_Knob.pdf

> **GS/C7 Stingray Sill Plate** *Stingray sill plate replaces original.* http://netwelding.com/Sill\_Plate.pdf

GS/C7 Nylon Bra Nylon Bra Stops Bugs. Fits with Stage 3 Winglets http://netwelding.com/Nylon\_Bra.pdf

**GS/C7 Clutch Fluid Change** *Clutch fluid after 3000 miles gets dirty* http://netwelding.com/Clutch\_Fluid.pdf

C7 Carbon Fiber Hood Vent Replaces Plastic Hood Vent http://netwelding.com/Hood\_Vent.pdf

GS/C7 Cold Air Intake Low Restriction Air Filter & Duct http://netwelding.com/Cold\_Air\_Intake.pdf

GS/C7 Soler Modified Throttle Body For Improved Throttle Response http://netwelding.com/Soler\_Mod\_TB.pdf

Garmin GPS for GS Cubby Garmin Mounts in GS Cubby & Apple CARPLAY http://netwelding.com/GPS\_In\_Cubby.pdf

GS Splitter Stage 3 Winglet Stage 3 Winglets Integrate with Spats http://netwelding.com/Stage\_3\_Winglets.pdf

Copyright by WA Technology, LLC





























How Our '34 ProStreet Rod Was Designed and Built http://netwelding.com/Engineering%20Street%20R od%203-08.pdf

#### **Motorsports Welding Article**

Wrote a 5 Page Article for AWS March 2018 Journal Covers NHRA and NASCAR Chassis Design http://netwelding.com/Motorsports\_Welding\_2018.pdf



Copyright by WA Technology, LLC